



Forced Performance Inc.

671 New Hope Road West
McKinney, Texas 75071
Phone: 972-984-1800
Fax: 972-984-1802

June 2, 2015

Subaru Oil Supply Lines

It is imperative that you do not use the factory oil feed line on your Forced Performance turbocharger. Doing so will cause failure in a very short period of time and we are not liable for turbos destroyed due to improper lubrication. To alleviate this issue all new Subaru turbos will now include our oil line and must be used failure to do so will void our complimentary repair policy if the turbo is to become damaged.

Below you will find a picture of a stock Subaru oil supply line notice that there are many restrictions in place for the factory turbocharger that would otherwise destroy a brand new Forced Performance turbocharger.

